ECS/EMD Configuration Change Request						Page 1 of Page(s)					
1. Ori	ginator	2. Log Date:	3. CCR #:		4. Rev:	5.	Tel:		6. Rm #:	7. Org.	
Robert \	Westbrook <b>04/12/2005 05-0</b>		05-010	60			301-614-5084		N125A		
8. CCR Title: Removal of X terminals from GDAAC											
9. Originator Signature/Date					10. Class						
Robert Westbrook /s/ 04/11/2005				ı	ı	CCR					
13. CCR Sponsor Signature/Date				14. Category of			_		15. Priority: (If "Emergency"		
Gary Roth /s/ 04/11/2005					Update ECS/EMD Baseline Doc fill in Block 27). Routine						
16. Documentation/Drawings Impacted (Review and submit 1					7. Schedule 18. CI(s) Affected:				ed:		
19. Release Affected by this Change: 20. Date due							1. Estimated Cost: one - Under 100K				
22. Source Reference: □NCR (attach) □Action Item □Tech Ref. □GSFC □Other:											
23. Problem: (use additional Sheets if necessary) The Xterminals are nearing end of life and need to replaced.											
24. Proposed Solution: (use additional sheets if necessary) GDAAC wants to remove the Xterms from this location. This will help reduce the amount of equipment required to be maintained. Landover has a need for the old terminals and has requested that we return the hardware to them. In order to support the Xterm removal, other GDAAC equipment will need to be relocated. In addition to the Xterms, we are returning additional unused hardware. The relocation, renaming, and a list of items being returned has been detailed in the attachment.											
25. Alternate Solution: (use additional sheets if necessary) Xterminals could be replaced with PC running Linux or SUN Blades.											
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) As Xterminals fail their replacement will become more and more difficult.											
27. Justification for Emergency (If Block 15 is "Emergency"):											
28. Sit	:e(s) Affected: □E □E	EDF PVC VATC	EDC ⊠ □Other	GSFC	□LaRC		NSIDC	SMC	C AK C	]JPL	
29. Boa	rd Comments:				30. V	Vork .	Assigned T	o:	31. CCR 0	Closed Date:	
	DV CCB Chair (Sign Peters /s/ 4/14/05		<b>Disposition:</b> Ap	oproved vd/ECS	App/Co	om. [	Disapproved	Wi	ithdraw Fwo	d/ESDIS ERB	
33. EDI	F CCB Chair (Sign/I	Date):	Disposition: Ap	proved	App/Co	m. I	Disapproved	l W	ithdraw Fwo	/ESDIS ERB	
			Fv	vd/ECS							
34. EC	S CCB Chair (Sign/I	Date): D	isposition: App	proved	App/Cor	n. I	Disapproved	l W	ithdraw Fw	d/ESDIS ERB	

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV

Fwd/ESDIS

## **ADDITIONAL SHEET**

CCR #: 05-0160 Rev: **Originator:** Office: Telephone: Title of Change: B0 X-terms Removal g0spx02 not connected to network already retired g0spx03 "C101-C, console position #42 replace with g0ais08" g0ais08 C101 Sun Blade 100 Relocate to C101-C, console position #42 g0spx04 "Distribution Tech, C101-C, console position #24" g0spx05 "C101-C, console position #41" "replace with g0ais07" g0ais07 C101 Sun Blade 100 relocate to C101-C, console position #41 g0spx08 "C101-C, console position #40 replace with M&O g0mos24" g0mos24 N125-7 Sun Blade 100 relocate to C101-C, console position #40 g0spx09 "C101-C, console position #31 replace with M&O g0mos08" g0mos08 N126-10 Sun Blade 100 relocate to C101-C, console position #31 g0aix03 not connected to network already retired g0aix04 "C101-C, console position #39 replace with g0ais09" g0ais09 C101 Sun Blade 100 relocate to C101-C, console position #39 g0aix13 "Test String, C101" retire g0aix14 "Test String, C101" retire g0aix15 "Test String, C101" retire g0aix16 "Test String, C101" retire g0aix17 "Test String, C101" retire g0aix18 not connected to network already retired g0aix19 "C101-C, console position #33 replace with g0dms04" g0dms04 "C101-C, #17" Sun Blade 100 relocate to C101-C, console position #39 g0aih20 "Test String printer, C101" relocate N126-K Renaming of machines То From g0ais08 198.118.210.135 g0sps03 198.118.210.135 g0ais07 198.118.210.131 g0sps05 198.118.210.131 g0mos24 10.1.198.52 g0sps08 198.118.210.18 g0mos08 10.1.198.164 g0sps09 198.118.210.29

All M&O and B0 X-terminals, the 8mm stacker that was attached to g0mss02, and a Sun storage array that was attached to g0ais10 and g0ais11 shall be returned to Landover.

G0dug01 and g0mop69 has been returned to Landover so there IP addresses are available for reuse.

CM01AJA00 Revised 10/2/03 *ECS/EMD*